Single Channel Instructions

- Connect the digital display cable to the weigh pad. Turn the display on and allow it to warm up for 1 minute.

- Push zero if display is not on "0". Capacity of system is 400 lbs unless marked otherwise.

- Display unit will operate on charger or battery (battery recommended). Low battery indicator is a flashing RED light. Connect charger. LED turns green (green LED does not go out when battery is charged). Charge time is 12 - 24 hours.

Keep this system clean and dry.
Do not drop pad or display.
Avoid electrostatic discharge.