



Push **ON** to turn gauge on. Gauge shuts off automatically after 3 minutes (not if in use - reading pressure). Turn back on if needed. Gauge auto-zeros at turn on. If zeroing is needed push **ON** and hold for 3 seconds.

- DO NOT DROP THE UNIT. KEEP IT CLEAN AND DRY DO NOT EXPOSE TO STRONG ELECTROMAGNETIC FIELDS (caster/camber gauge magnets?). **DO NOT EXCEED RATED PRESSURE.** This unit runs approx. 500 hours on internal battery. When the Low Battery indicator appears in the upper right of the display (see below) replace with a quality CR 2032 'coin' style battery. Access is on the back of the gauge.

To convert to metric – BAR or other – follow the instructions below:

- Turn gauge on. When 0.0 appears push AND HOLD the **UNITS** button on the right side.
- After 3 seconds the units indication will start to flash. This is along the top of the display. PSI on the upper left.
- Release the UNITS button and then push again to change. Options are PSI, BAR, Kgm/cm² and kPa.
- Once you have reached your selection stop pushing the button. The gauge will return to normal function in 5 seconds.

Units choice:
Psi here

Bar here

Reads to .2 psi
0-60 psi

UNITS button

Low Battery indicator