



For support relating to this compressor and A/C system related questions, contact:
Sanden Tech @ 1-972-442-8400

Any warranty returns should be done through the distributor the compressor was purchased through.

For support relating to Holley accessory brackets and related bracket installation questions, contact:
Holley Tech @ 1-866-464-6553

A/C COMPRESSOR P/N 199-101 & 199-102

For adapters and fitting, see the Vintage Air catalog <http://www.vintageair.com/catalog.asp>

To download a complete instruction manual, go to the following website:
<http://www.sanden.com/index.php?tag=MTExOTk3OTEwNw6>

*Tech Tips can be found at www.sanden.com

SANDEN TECHNICAL SUPPORT
1-972-442-8400

IMPORTANT! LS and similar engines are capable of high RPMs that can damage an A/C compressor's complex moving internal parts. A tach or TPS monitoring RPM switch, such as NOS P/N 15982NOS, should be configured to deactivate the compressor clutch when the engine is above 4000 RPM.

WARNING! Failure to install part 15982NOS or similar will VOID the A/C compressor warranty.

NOTE: See wiring diagram on the next page for 15982NOS installation.

Wiring diagram

